

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2012 Levee Inspection Results**

**Sutter Maintenance Yard Hamilton Bend**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2012 Levee Inspection Results**

**Sutter Maintenance Yard Hamilton Bend**

Waterway			Bank	Unit Miles
Unit No. 01 Feather River Hamilton Bend			Right	3.22
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/28/2012 - 3/28/2012			
DWR Inspector	Clay Thomas			
Accompanied By	Jason Cooper Sutter Yard			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Sutter Maintenance Yard Hamilton Bend**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Feather River Hamilton Bend				Right	3.22	03/28/2012 03/28/2012	Clay Thomas	

  

LMR No.	Levee Mile		Category	Item	Location *	Rating ** +	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1			Earthen Levee	Vegetation	LS A/W Ma	V1 : Control annual grass and weeds on the levee slopes and easements.		39.456568 ° -121.639400 °	° °	1
DWR ID: DWR_ST0005_01_s_2012_1										
2			Earthen Levee	Vegetation	WSA/W Ma	V1 : Control annual grass and weeds on the levee slopes and easements.		39.456568 ° -121.639401 °	° °	2
DWR ID: DWR_ST0005_01_s_2012_2										
3			Earthen Levee	Operations & Maintenance Manuals	WS Ma	A		° °	° °	3
DWR ID: DWR_ST0005_01_s_2012_3										
4			Earthen Levee	Emergency Supplies & Equipment	WS Ma	A		° °	° °	4
DWR ID: DWR_ST0005_01_s_2012_4										
5			Earthen Levee	Flood Preparedness & Training	WS Ma	A		° °	° °	5
DWR ID: DWR_ST0005_01_s_2012_5										

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement